



**REST
ROOMS**

LADIES

Sagamore Hill National Historic
Site

Oyster Bay, New York

Nassau Co.

Photograph taken by Park Staff
November 1978. Negative at Park.

10/20

Ice House

(1885)

MAY 7 1979



Sagamore Hill National Historic
Site

Oyster Bay, New York

Photograph taken by Park staff
November, 1978

russe CJ

20710

Gray Cottage

MAY 7 1979

(1910)



Sagamore Hill National Historic Site
Oyster Bay, New York

Chicken House

MAY 7 1979

Grassman Co

The first window on the left belongs to the tool shed, the next three belong to the Chicken House *3 of 10*




Sagamore Hill National Historic Site
Oyster Bay , New York *Norman C*

Windmill

MAY 7 1979

A reconstruction of the 1905
windmill built by the National Park
Service in 1971. *4 of 10*





Sagamore Hill National Historic
Site

Oyster Bay, New York.

Photograph taken by Park Staff
November, 1978. Negative
at Park

Curson CW 5-21-78

Carriage House and Tool Shed
MAY 7 1979

Double door - Carriage House

Single door- Tool Shed

Rear portion is Chicken House



Sagamore Hill National Historic
Site

Oyster Bay, New York

Photograph taken by Park Staff
November, 1978. Negative at
Park.

Nassau Co

6 of 10

Gardener's Shed

MAY 7 1979



Sagamore Hill National Historic Site
Oyster Bay, New York

MAY 7 1979

Barn (1907) MAY 7 1979

Masson C

Photograph taken November, 1978,
Negative at Park

7-211



Sagamore Hill National Historic
Site
Oyster Bay, New York

Photograph taken by Park staff,
November, 1978. Negative at
Park.

Theodore Roosevelt Home (1884-1885)

MAY 7 1979

Garrison Co

70710



Sagamore Hill National Historic Site
Oyster Bay, New York

MAY 7 1979

Theodore Roosevelt Home (1884-1885)
(1905 North room addition on left)
Crasson Co

Photograph taken November, 1978

80210



MAY 7

1979

Theodore Roosevelt Home

(1884-1885)

Massachusetts

May 10

